
rms Roughness



D/S	rms Roughness
0.25	3.2
0.33	2
0,3	2
0.5	3.4
1	3.1

FIG. 1